

## Printer Migration Quick Glance

This document provides helpful recommendations of replacement products and new part numbers to assist you in selecting the best replacement to the 3400 and 4420 printers that no longer appear in the Intermec North American Price Guide.

<b>3400e</b>		<b>Recommended Replacement – PM4i</b>		<b>Price Guide Status</b>
3400E01000200	3400 with Parallel Port	PM4C901000300020	PM4i with Parallel Port	Available
3400E01400200	3400 with Ethernet	PM4C910000300020	PM4i with Ethernet	Preferred
3400E01500200	3400 with 802.11 b/g	PM4C940000300020	PM4i with 802.11 b/g	Available
3400E01000201	3400 with Parallel Port	PM4C911000301020	PM4i with additional Ethernet; Parallel Port; Self Strip	Available
<b>4420</b>		<b>Recommended Replacement – PX4i</b>		<b>Price Guide Status</b>
4420E01000200	4420 with Parallel Port	PX4B911000300020	PX4i with Ethernet, Parallel Port	Available
4420E01400200	4420 with Ethernet	PX4B910000300020	PX4i with Ethernet	Available
4420E01500200	4420 with 802.11 b/g	PX4B940000300020	PX4i with 802.11 b/g	Available
4420E01000201	4420 with Parallel Port, Self Strip	PX4B911000301020	PX4i with additional Ethernet, Self Strip	Available
<b>3400e with 400 dpi</b>		<b>Recommended Replacement – PX4i</b>		<b>Price Guide Status</b>
3400E01000400	3400 with Parallel Port	PX4B911000300040	PX4i with Ethernet, Parallel Port, 400 dpi	Available
3400E01400400	3400 with Ethernet	PX4B911000300040	PX4i with Ethernet, Parallel Port, 400 dpi	Available
3400E01000401	3400 with Parallel Port, Self Strip	PX4B911000301140	PX4i with Ethernet, Parallel Port, Self-strip, RTC, 400 dpi	Available
3400E01400401	3400 with Parallel Port, Self Strip	PX4B911000301140	PX4i with Ethernet, Parallel Port, Self-strip, RTC, 400 dpi	Available