


Kits > 7602-K161 Serial Port Expansion Module

Serial Port Expansion Module

Introduction

This kit provides a Serial Port Expansion Module for RealPOS XR4.


Kit Content



70601


Installation Procedure

1. Lay the terminal face down on a flat surface.
2. If a Cable Management Bar is present, loosen the captive screws (2) and remove the Bar.



OCP-70238

3. Connect the 12V Powered USB Cable to the connector on the terminal.



70600

4. Install the Cable Management Bar and tighten the thumbscrew to secure the cables.